

SECRET

0034Z 27 MAR 63

DIRECTOR

**PRIORITY**

PRIORITY

OPS (1-2-3-4-5-6)

S/C (7)

TOR: 0131Z 27 MAR 63

IN 70300

[REDACTED]

[REDACTED]

[REDACTED]

25X1

25X1

1105/261610Z/359

[REDACTED]

1. [REDACTED] OTHER NUMBER N/A

2. N/A

3. X1 - RECORDER FAILED DURING FIRST FEW MINUTES OF MISSION TAKEUP  
MOTOR FAILED.

[REDACTED]

1. 9A.

2. BEACON OPERATION - GOOD.

[REDACTED]

1. 14/FAIR/GOOD/GOOD.

25X1

2. PILOT INDICATED SOME [REDACTED] WE HAVE NO TEST  
EQUIPMENT TO CHECK SYSTEM.

[REDACTED]

2. FAILED AT 2003Z. CAUSE OF FAILURE AS YET UNDETERMINED.

SECRET

25X1

[REDACTED]

IN 70300

S E C R E T

PAGE TWO

25X1

[REDACTED]

1. 21

2. NO ACTIVITY INDICATED

25X1

[REDACTED]

N/A

RADIO AND NAVAIDS

25X1

GROUND REPORTED [REDACTED] WEAK DURING TURNS.

END OF MESSAGE

S E C R E T